

3G FOOTBALL PITCH - MAJOR REPAIRS AND REFURBISHMENT



Before

The issue with a lot of community surfaces based within inner city estates is that they get a huge amount of use. At Broadway Market, the centre of the pitch was worn out with areas through to the backing of the grass and subsequent damage to the base. The grass pile was sitting completely flat with the rubber and sand compacted right into the base of the pile.

The challenge

With very limited access, less than 1m concrete tunnel, the brief was to repair shock pad damage and replace the damaged areas of 3G grass with the nearest possible match. Rejuvenate the whole surface so that it was safe and playable for the community.

The surface

With very limited access, less than 1m concrete tunnel, the brief was to repair shock pad damage and replace the damaged areas of 3G grass with the nearest possible match. Rejuvenate the whole surface so that it was safe and playable for the community.

The result

The large community are now able to safely enjoy and play on the surface. The surface was worn out through the whole communities' love of sport, especially football.

Call us or email today for a free quote